

Just a reminder that CAN-hi and CAN-low wires for LHCM on 2021 touring models are flipped.

